

**CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD—  
LOS ANGELES REGION**

101 CENTRE PLAZA DRIVE  
MONTEREY PARK, CA 91754-2156  
(213) 266-7500

SFUND RECORDS CTR  
2166-95559



July 1, 1993


Rienzie Pintoe  
Nupla Plastic Corporation  
11912 Sheldon Street  
Sun Valley, Ca. 91352

**WELL INVESTIGATION PROGRAM - SOIL GAS SURVEY WORKPLAN  
(FILE NO. 111.0788)**

We have reviewed "Workplan for a Soil Gas Survey" dated June 17, 1993, prepared by Environmental Support Technologies and found it insufficient and inadequate to meet our Workplan Requirements for Soil Gas Investigation as your workplan failed to contain a coarse survey to evaluate the entire site as indicated in our Workplan Requirements, Survey Design, Item 2 (copy enclosed, again). Your revised Workplan must contain a sufficient number of additional soil gas points to adequately cover the entire site.

Three (3) copies of your revised Soil Gas Investigation Workplan are due to this Regional Board by August 6, 1993.

If you have any questions regarding this matter, please contact Mr. Jimmie Woo at (213) 266-7591.

  
HUBERT H. KANG  
Senior Water Resource  
Control Engineer

Enclosure

cc: w/o Enclosure  
Mr. Chris Stubbs, U.S. EPA Region IX  
Mr. Bill Jones, Los Angeles County - Forester and Fire Warden  
Mr. Kirk Thomson, Environmental Support Technologies